



How to solve the problem:

For time measurement a dedicated action is available.

Use qualifier S and R for pressure control in order to avoid specifying pressure control parameters for each step.